ASB 002 0014

Facility Name:	Asbestos Dump Site	
Location:	Millington, New Jersey	
EPA Region:	II	
Person(s) in Cha	irge of the Facility:	Morris Trichon
		•····
Name of Reviewer	Renee R. Bobal	Date: 8/6/82
General Descript	ion of the Facility:	
types of hazard contamination in needed for ration. The Asbestos During	lous substances; locati coute of major concern; ing; agency action, etc mp site in Millington, N	types of information
of dumping by s	everal asbestos processi	ng companies. Since
the time the du	mping was stopped, the s	ite has been covered
over by soil an	d vegetation. Although	the base of the dump along
the river bank	has been reinforced with	riprap, erosion and weathering
	all areas of asbestos. Imercuric acetate has be	Allegations also have been en dumped at the site.
Scores: SH = 39	.61 (Sgw = 0 Ssw	-68.53s _a - 0)
SFE -	0	
s _{DC} = 2	5	

HRS COVER SHEET

	G	ROUN	D WAT	ER	R	TUC	E WOR	K S	HEET	•		
	Rating Factor					d Vali			Multi- plier	Score	Max. Score	Ref. (Section)
1	Observed Release	.	0				45 -		1	0	45	3.1
	if observed releas	_						_				
2	Route Characteris Depth to Aquifer of		0	1	2	3		- 11	2		6	3.2
	Net Precipitation Permeability of the Unsaturated Zone		0	1	2	3			1		3 3	
	Physical State		0	1	2	3			1		3	
			Total Res	rte C	ha	racter	istics Sco	re			15	
3	Containment		0	1	2	3	·		1		3	3.3
4	Waste Characteris Toxicity/Persisten Hazardous Waste Quantity		0	3	6 2	9 12 3 4	15 18 5 6 7	8	1		18 8	3.4
			Total War	ste C	⊃ha	racter	istics Sco	re			26	
5	Targets Ground Water Use Distance to Neare Well/Population Served	=	0 12 24	1 4 16 30	2 6 18 32	3 - 8 10 20 35 40			3		9 40	3.5
700					_	ets S	core				49	
<u></u>			1 × 4	•	<u> </u>) × [<u> </u>				57.330	
7	Divide line 6 b	y 57,330	and multip	My b	y 1	00	Sgw-	C	*			

^{*} As bestos is an inschible silvente which does not migrate throughpround water; no evidence exists at present. Also, the soils and geology of the area do not promote migration to groundwater.

		SURFAC	CE W	ATE	R RC	OUTE WOR	RK SH	EET		
	Rating Factor				e One		Multi-	Score	Max. Score	Ref. (Section)
o	Observed Release		0		(45)	1	45	45	4.1
	If observed release	-								
2	Facility Slope and		0	1 2	3		1		3	4.2
	Terrain 1-yr. 24-hr. Rainfall Distance to Neares		_	1 2			1 2		3 6	
	Water Physical State		0	1 2	3		1		, 3	
		To	tal Rou	ie Ch	aracter	istics Score			15	
3	Containment		0	1 2	. 3		1		3	4.3
•	Waste Characterist Toxicity/Persistend Hazardous Waste Quantity		0	3 6 1 2	9 12 3 4	19 18 3 6 7 8	1	15	18	4.4
		Tol	Wes	ite Ch	eracter	ristics Score		20	26	
3	Targets Surface Water Use Distance to a Sens Environment Population Served	sitive	6	1 2 1 2 4 6	3 3 8 10		3 2	9 C 40	9 6	4.5
	to Water Intake Downstream) 12 24		20 35 (40)	-	,		
_					gets S			49	55	
0	If line 1 is 45. if line 1 is 0, m	multiply [] nultiply []						41cc	64,350	
	Divide line 6 by	44.350 and	multip	ly by	100	5 sw -68.	V 3			

			AIR R	DUTE	E WO	RK SHI	EE	r			
	Rating Factor				d Value One))		Multi- plier	Score	Max. Score	Ref. (Section)
0	Observed Release		0		4	5		1	0	45	5.1
	Date and Location	:						•	_		·
	Sampling Protocol	•									
•	If line 1 is 0, d		. Enter on	`							
2	Waste Characterist Reactivity and Incompatibility Toxicity Hazardous Waste Ouantity	tics	. 0	1 2 1 2 1 2	3	5 6 7	8	1 3 1		3 9 8	5.2
			Total Was	ite Cha	aracteri:	stics Scor	*			20	
3	Targets Population Within 4-Mile Radius Distance to Sensiti Environment Land Use	w e	0	24 27	3			1 2 1		30 6 3	5.3
			Tot	al Tan	gets Sc	ore				39	
4	Multiply 1 x 2	× 3								35,100	88 80
3	Divide line 4 by	35,100	and multip	ly by 1	100	•- 0)				88

 $\textbf{WORKSHEE}\textbf{T} \ \textbf{FOR COMPUTING S}_{\textbf{M}}$

		- 		_								
	Rating Factor		(Ci	gne	0	(en	•		Multi	1 50018	Max. Score	Ref. (Section
0	Containment	tainment 1 3 1							3	7.1		
2	Waste Characteristics										<u> </u>	7.2
	Direct Evidence	0			3				1		3	• • •
	Ignitability	. 0	1	2	3			•	1		3	
	Reactivity		1		3				1		3	
	Incompatibility	ō		2	3				1		3	
	Hazardous Waste Ouantity	; ;		2	3	4	5	6 7	8 1	•	8	
	[Total Wa				100	etic	* Score		T	20	
_				_			-			<u> </u>		
3												7.3
	Distance to Nearest	0	1	2	3	4	5		1		5	
	Population -		_	_	_				_		_	
	Distance to Nearest Building	0	1	2	3				1		3	
	Distance to Sensitive		1	2	3				1		3	
	Environment	•		•	•				•		•	
	Land Use	0	1	2	3				1		3	
	Population Within	0	1	2	3	4	5		1		5	
	2-Mile Radius											
	Buildings Within	0	1	2	3	4	5		1		5	
	2-Mile Radius											
		То	tel '	Targ	ets	S c	ore	· 			24	
1	Multiply 1 x 2 x	3									1,440	

		DIRECT C	ONTACT	WORK SH	EET	-		
	Rating Factor		Assigned Va (Circle One		Multi- plier	Score	Max. Score	Ref. (Section)
0	Observed Incident	()	45	1	0	45	8.1
		proceed to line [2			•	·		
2	Accessibility .		1 2 3		1	3	3	6.2
3	Containment	0	15		1	15	15	6.3
4	Waste Characteris Toxicity	itics 0	1 2 3		5	10	15	8.4
3	Targets Population Within 1-Mile Radius Distance to a Critical Habitat	• 6	1 2 3	4 5	4	12	20	8.5
	1	Te	otal Targets	Score		12	32	
<u>s</u>	If line 1 is 45, if line 1 is 0, m	multiply 1 x 4 nultiply 2 x 3		<u>ទ</u>		5400	21,600	
7	Divide line 6 by	y 21,600 and multip	ply by 100	soc - 2:	5			

DOCUMENTATION RECORDS FOR HAZARD RANKING SYSTEM

INSTRUCTIONS: The purpose of these records is to provide a convenient way to prepare an auditable record of the data and documentation used to apply the Hazard Ranking System to a given facility. As briefly as possible summarize the information you used to assign the score for each factor (e.g., "Waste quantity = 4,230 drums plus 800 cubic yards of sludges"). The source of information should be provided for each entry and should be a bibliographic-type reference that will make the document used for a given data point easier to find. Include the location of the document and consider appending a copy of the relevant page(s) for ease in review.

FACILITY NAME	: Asbestos	Dump Site	
LOCATION:	Millington	, New Tersey	•

1 OBSERVED RELEASE

Contaminants detected (5 maximum):

No analytical results exist.

As bestor is an insoluble silvate which does not imprate through ground water. At present, no Score is O. migration of asbestor. Furthermore, the Rationale for attributing the contaminants to the facility: Souls and scolor of the area do not promote migration to groundwater.

Soils overburden day groundwater.

Soils overburden day groundwater.

Ceft 6,7 - Professional judgem Bedrock - basalt. - Reft 6,7 by FIT hydrogenogists

2 ROUTE CHARACTERISTICS

Depth to Aquifer of Concern

Name/description of aquifers(s) of concern:

Depth(s) from the ground surface to the highest seasonal level of the saturated zone [water table(s)] of the aquifer of concern:

Depth from the ground surface to the lowest point of waste disposal/ storage:

Net Precipitation

Mean annual or seasonal precipitation (list months for seasonal):

Mean annual lake or seasonal evaporation (list months for seasonal):

Net precipitation (subtract the above figures):

Permeability of Unsaturated Zone

Soil type in unsaturated zone:

Permeability associated with soil type:

Physical State

Physical state of substances at time of disposal (or at present time for generated gases):

Method(s) of waste or leachate containment evaluated:

Method with highest score:

4 WASTE CHARACTERISTICS

Toxicity and Persistence

Compound(s) evaluated:

Compound with highest score:

Hazardous Waste Quantity

Total quantity of hazardous substances at the facility, excluding those with a containment score of 0 (Give a reasonable estimate even if quantity is above maximum):

Basis of estimating and/or computing waste quantity:

5 TARGETS

Ground Water Use

Use(s) of aquifer(s) of concern within a 3-mile radius of the facility:

Distance to Nearest Well

Location of nearest well drawing from aquifer of concern or occupied building not served by a public water supply:

Distance to above well or building:

Population Served by Ground Water Wells Within a 3-Mile Radius

Identified water-supply well(s) drawing from aquifer(s) of concern within a 3-mile radius and populations served by each:

Computation of land area irrigated by supply well(s) drawing from aquifer(s) of concern within a 3-mile radius, and conversion to population (1.5 people per acre):

Total population served by ground water within a 3-mile radius:

SURFACE WATER ROUTE

1 OBSERVED RELEASE

Contaminants detected in surface water at the facility or downhill from it (5 maximum):

Asbertor EPA testr of Parrail Valley Ninter Commission rai unter 10/77
river intuke
769,000 fisero/liter

Rationale for attributing the contaminants to the facility:

Arberter dinjo en Parraie River - no other arbentos sources known

2 ROUTE CHARACTERISTICS

Facility Slope and Intervening Terrain

Average slope of facility in percent:

Name/description of nearest downslope surface water:

Average slope of terrain between facility and above-cited surface water body in percent:

Is the facility located either totally or partially in surface water?

Facility is bentul on the south of the Tarrier River and the coaste crafes into

the River => off-cite observation by Fred C. Heart Associator personnal

Is the facility completely surrounded by areas of higher elevation?

1-Year 24-Hour Rainfall in Inches

Distance to Nearest Downslope Surface Water

Physical State of Waste

3 CONTAINMENT

Containment

Method(s) of waste or leachate containment evaluated:

Method with highest score:

4 WASTE CHARACTERISTICS

Toxicity and Persistence

Compound(s) evaluated

Compound with highest score:

Hazardous Waste Quantity

Total quantity of hazardous substances at the facility, excluding those with a containment score of 0 (Give a reasonable estimate even if quantity is above maximum):

Basis of estimating and/or computing waste quantity:

5 TARGETS

Surface Water Use

Use(s) of surface water within 3 miles downstream of the hazardous substance:

15

Distance to a Sensitive Environment

Distance to 5-acre (minimum) coastal wetland, if 2 miles or less:

Mone

Distance to 5-acre (minimum) fresh-water wetland, if I mile or less:

Menz

Distance to critical habitat of an endangered species or national wildlife refuge, if I mile or less:

? I will Great Champ Wildlife Refine ANDED Div. of Fish, Gam, & Wildlife

Population Served by Surface Water

Location(s) of water-supply intake(s) within 3 miles (free-flowing bodies) or 1 mile (static water bodies) downstream of the hazardous substance and population served by each intake:

Farrice Valley liate-Countries

so, oco real

3 from Marque Reversir

abuter fibers in now water, is distance is o'

NSB 002 003

Computation of land area irrigated by above-cited intake(s) and conversion to population (1.5 people per acre):

none

Total population served:

Mone

Name/description of nearest of above water bodies:

none

Distance to above-cited intakes, measured in stream miles.

1 OBSERVED RELEASE

Contaminants detected:

Mone - Scare = C

Date and location of detection of contaminants

Methods used to detect the contaminants:

Rationale for attributing the contaminants to the site:

2 WASTE CHARACTERISTICS

Reactivity and Incompatibility

Most reactive compound:

Most incompatible pair of compounds:

Toxicity

Most toxic compound:

Hazardous Waste Quantity

Total quantity of hazardous waste:

Basis of estimating and/or computing waste quantity:

3 TARGETS

Population Within 4-Mile Radius

Circle radius used, give population, and indicate how determined:

0 to 4 mi

0 to 1 mi

0 to 1/2 mi

0 to 1/4 mi

Distance to a Sensitive Environment

Distance to 5-acre (minimum) coastal wetland, if 2 miles or less:

Distance to 5-acre (minimum) fresh-water wetland, if 1 mile or less:

Distance to critical habitat of an endangered species, if I mile or less:

Land Use

Distance to commercial/industrial area, if I mile or less:

Distance to national or state park, forest, or wildlife reserve, if 2 miles or less:

Distance to residential area, if 2 miles or less:

Distance to agricultural land in production within past 5 years, if I mile or less:

Distance to prime agricultural land in production within past 5 years, if 2 miles or less:

Is a historic or landmark site (National Register or Historic Places and National Natural Landmarks) within the view of the site?

ROM	Dennis	Faherty

DATE December 16, 1980

SUBJECT Asbestos Dumps, Great Swamp and Millington

August 28, 1980

C. Bartolone and D. Faherty inspected the asbestos located at the Great Swamp. Mrs. Sims and two students accompanied us to the site. We observed at "nature path" made from asbestos type housing tiles. The path is over 200 yards long, and at least one foot deep. A sample of the shingles was taken. D. Faherty advised Mrs. Sims that the situation will be referred to Solid Waste.

August 29, 1980

D. Faherty called the Bureau of Hazardous Waste. Mr. Harvey Duhamil informed D. Faherty that the asbestos type shingle are not considered hazardous. He added that the asbestos type shingles are normally disposed of in regular landfills.

October 8, 1980

Anne Marie Cottone, Star Ledger, reporter, notified Dennis Faherty that she had received a report from Mike Barga (201-766-4210) that raw asbestos was also dumped at the Great Swamp "nature trail".

November 25, 1980

D. Faherty reinspected the asbestos "nature path" in the Great Swamp Refuge. It had rained steadily the day before. The purpose of this inspection was to take samples to determine if the asbestos was entering the adjacent water bodies.

I observed at a lower elevated section of the nature path, that the asbestos fragments were in fact submerged in the water. I took two grab samples of the decomposing tile fragments on the bottom sediment of Great Brook. It appears the shingles are dissolvi because there is a white muck attached to the fragments over the darker sediment.

__cember 3, 1980

Arrived at the Millington train station to meet Tom Berry, N.J. Public Interest Research Group. Mr. Berry had agreed to meet and show me the three other asbestos dump sites in the Great Swamp and vicinity.

Tom Berry arrived at the Milliagton train station. The first site we inspected was the large aspestos hill located behind the Tifa Ltd. Plant, 50 Division St., Millingto The asbestos hill was was the result of years of dumping by the National Gypsum Compan the previous owners of the property. I observed large areas of exposed asbestos along the hill. The asbestos was both loose sludge and pieces of the raw mineral.

The hill is directly adjacent to the Passaic River (source of drinking water). I took two grab samples of the exposed asbestos.

Mr. Berry informed me that the D.E.P. had taken the National Gypsum Company to court year or so ago. The D.E.P. had settled for having the asbestos covered over with a local soil.

The soil has since erode in large areas, again exposin the asbestos. Each rain will wash this exposed asbestos directly into the Passaic River, located less than fifteen feet away.

We then proceeded to inspect the other dumps in the Great Swamp Refuge.

On the dead end side of Whitebridge Raod, there is a private residential driveway made of the same asbestos shingle fragments found at the nature trail. Mr. Berry also that there is an asbestos dump in the rear of the driveway.

The other dump site is located at the Pine Valley Tree Service driveway. The driveway is made of asbestos shingle fragments and there is an alledged dump in the rear of the property.

Mr. Berry informed me that Tifa Ltd.is planning on expanding their facility, and build a parking lot on top of the asbestos hill. Mr. Berry said that the city has the detained mr. Berry also told me that an ex-employee of National Gypsum Company, Michael Burke, (201-766-4210) has addition first hand information regarding the dumping practices that occurred years ago.

DF:dg

SB 002

CE.00 20

farms (shingle fragment loose sludge, raw mineral). It each site, the asbestos is directly exposed to the environment. There is evidence that the asbestos shingles degrade into fibers in the water, as observed at the nature trail in the Great Swamp. The asbestos hill behind the Tifa Ltd. facility has large exposed areas of asbestos sludge easily capable of eroding and washing directly into the Passaic River. The nature trail and driveway sites could pose health problems to individuals during dry weather periods by raising dangerous asbestos dust into the atmosphere.

There is also a report by an ex-employee that chemicals such as phenol mercury acetatowas dumped in the asbestos hill behind the Millington plant.

<u>Recommendations</u>: The exposed asbestos at the driveway sites and the nature trail should either be physically removed and disposed of at a secure landfill or at the very least, should be completely covered over with a clay type soil, and then with an additional layer of stone.

Because of the close location of the asbestos hill to the Passaic River, an immediate effort should be made to properly cover over the exposed areas.

Perhaps a plan can be drawn up utilizing the asbestos hill as the disposal site for the asbestos at the nature trail. The details of this plan would have to be negotiate with Tifa Ltd., Bureau of Solid Waste, the National Gypsum Company and the Division of Hazard Management.

In addition to securely covering or removing the asbestos from the driveways and hill, I feel observation well should be installed in the asbestos hill to confirm or deny the report that chemicals were dumped there years ago. Samples should be taken to the extent of the contamination and impact on the environment, especially the Passaic Rive The Spill Fund may have to be activated if the Department feels that the clean up of the asbestos is an environmental priority.

der

BIBLIGRAPHY OF INFORMATION SOURCES USED TO

APPLY THE HAZARD RANKING SYSTEM*

TITLE	DATE	AUTHOR/PUBLISHER	AVAILABLE FROM
1. Memo to Spill File, Asbestes Dumps, Great Swamp and Milleyton	12 10 80	Dennis Faherty, NIDEP	N J >E }
2. US Crectogie Survey Topographie Quadrangles Bernardsville, Chatham, Plainfield, Boundbrook, NJ	19 65	usc-s	. us us
3. Uncontrolled Hazardons Waste Site Ronking System - A User. Manual	6/10/82	US EPA	U.S. EPA
4. Conversation with Ella Phillapone of Passaic Rever Contestion + access to Content is likes	8/10/83	-	Passau River Coaleturi (201)766-755c
5. telephone conversation with UJDEP, Potable Water Division	8 0 82	-	NZDEP
Surface Formations of the Surface Formations of the Nathan of Fasare. Prepared by Rollin D. Sulisbury	\894	U SGS-N T	usus - N2
Sail Survey of Marris County, New Jersey	8 76	Soil Conservation Service	Soul Conservat Service

8.

9.

10.

^{*}Attach additional pages, if necessary.

LIST OF ATTACHED EXCERPTS OF

SUPPORTING DOCUMENTATION*

TYPE OF INFORMATION

SOURCE

1. There to Spill File, Asbestos Dimps, NJDEP Creat Swamp and Millington

2.

3.

4.

5.

6.

7.

8.

9.

10.

*Attach additional pages, if necessary.

SEPA	FENTIAL HAZARDOUS WA		·	TEGION	SITE A	IUMBER (10 b He)	
GENERAL INSTRUCTIONS: Compl tion on this form to develop a Tenta File. Be sure to include all approp tection Agency; Site Tracking Syste	tive Disposition (Section II). Friste Supplemental Reports in them; Hazardous Waste Enforceme	ile this form le file. Subm ent Tack For	in its entirety i n tit a copy of the f	the region orms to: \	ial Haz U.S. Er	rardous Wast nvironmental	e Log Pro-
	I. SITE IDENT	IFICATION					
A. SITE NAME		. STREET (or	other identifier)				
Aspestos Dump	Site	STATE	A Squ	LCLYC		12	
Millington		NJ	E. ZIP CODE	477			
1. NAME				ال عاما	Shone	K NUMBER 53-85	511
F Dans	thems — can	1some		α	7	6. ZIP CODE	
National by 3. STREET 4100 ST Internation (1)	nal Blds Dall	las	•	TX		7527	
T. NAME				2. TELE	PHONE	NUMBER	
TIFA _ L	td			(20)	٢٥٤	7 - 4 5	70
Millington				7.14		0794	ماا
I. SITE DESCRIPTION				100			<u> </u>
J. TYPE OF OWNERSHIP						•	
1. FEDERAL 2. STATE	E. 3. COUNTY 4.	MUNICIPAL	S. PRIVA	TE			
	II. TENTATIVE DISPOSITION	(complete th	is section lest)				
A. ESTIMATE DATE OF TENTATIVE DISPOSITION (mos, day, & yrs).	B. APPARENT SERIOUSNESS (F PROBLEM MEDIUM	⊉ 3. Low	U 4	NONE		
C. PREPARER INFORMATION			· · · · · · · · · · · · · · · · · · ·				
1. NAME RENÉE R T		201) 63	1- 6800	8	(mo., d	ley, & ym).	
	III. INSPECTION I			<u> </u>	113		
A. PRINCIPAL INSPECTOR INFORMAT	FION	. TITLE		- ,			
3. ORGANIZATION	<u>-</u> L			4. TELE	PHONE	NO.(8788 66	do & n
	4			<u> </u>			
8. INSPECTION PARTICIPANTS					***	PHONE NO.	
I - NAME	S. ORGANI	ZATION				PHONE NO.	
	·		·				
				Ĺ			
						· · · · · · · · · · · · · · · · · · ·	
C. SITE REPRESENTATIVES INTERVI		, residente)					
1. NAME	2. TITLE & TELEPHONE NO.			ADDRESS			
						 .	- >
							ASB
							8

0039

Continued From Front		in the second se			
		PECTION INFORMATION (C	ontinued)		
D. GENERATOR INFORMATION					
J. NAME .	2. TELEPHONE NO.	3. ADD		4. WASTE TYP	E GENERATE
National,	12.1 -0 0-	4100 HIVSF ENTE	Texas	1 .	
Couperem	(214) 653 - 85	Dallas	Texas	Hisbe	stos
٥,		1	;		
		· •		1	
				J	
. TRANSPORTER/HAULER	INFORMATION				
I. NAME	1. TELEPHONE NO.	3. AOO	RESS	4.WASTE TYPE	ETRANSPORTE
	1	.			
					
				1	
		1		1	
10 WALTE IS BESSELLE	ON SIZE AND AL 20 2002	950 70 054	15V DEC. 2175 E 1611 1711	T. 11850 500 0	ISBOSA
	2. TELEPHONE NO.	PED TO OTHER SITES, IDENT	3. ADDRESS	LS USED FOR D	-JPU3AL.
1. NAME	4. IELEPHONE NO.		J. AUURESS		
	1	1.			
		 			
	J	J			•
					·· ·
DATE OF INSPECTION (mo., day, & yr.)	H. TIME OF INSPECTI	ON I. ACCESS GAINED BY: (cr		(1 Cases)	
		. PERMISSION	2. WARRANT		
J. WEATHER (describe)		-			
		,			
		V. SAMPLING INFORMATIO)N		
A. Mark 'X' for the types of	semples taken and ind	cate where they have been s	ent e.g., regional lab, o	ther EPA lab,	contractor,
etc. and estimate when t	the results will be avail	able.			
	2. SAMPLE				4. DATE RESULTS
1.SAMPLE TYPE	TAKEN (mark'X')	3.3AMPC	E SENT TO:		AVAILABLE
S. SROUNDWATER					
		*	· 	<u></u>	
. SURFACE WATER					
- w.a.					
e. WASTE	1			į	
L AIR				1	
. RUNOFF	1 1		_		
					
£ spill	į į			[
					
g. \$01L					
		· · · · · · · · · · · · · · · · · · ·			
b. VEGETATION]]				
		···			
L. OTHER (opocity)					
					
. FIELD MEASUREMENTS T	AKEN (o.g., redlesstivity,	emicolvity, PH, etc.)			
1. TYPE	2. LOCATIO	N OF MEASUREMENTS	3.1	RESULTS	
•			1		
			1		
			1		
			 		
	1		j.		

Continued From Page 2				_			
		IV. SA	MPLING INFO	RM/	ATION (continued)		
C. PHOTOS							
1. TYPE OF PHOTOS			2. PHOTOS	N C	USTODY OF:		
	. AERIAL		1				
D. SITE MAPPEDY							
YES. SPECIFY LOCA	TION OF M	APS:	NS G-S -	Τ.	spegraphie Qu	ددر	drangle
E. COORDINATES		· · · · · · · · · · · · · · · · · · ·					
1. LATITUDE (degminsec	•)		. %	1 4	LONGITUDE (degminsec.)		
40°	40/4	15"	*	1	74°31'5	5	*
	· · ·		V. SITE INC	OR			· · · · · · · · · · · · · · · · · · ·
A. SITE STATUS			¥ u An				
1. ACTIVE (Those induc municipal sites which are bei for waste treatment, storage, on a continuing basis, even i quently.)	ing used or disposa		TIVE (Those no longer receive	1	3. OTHER (specify): (Those sites that include such inc where no regular or continuing use has occurred.)		
B. IS GENERATOR ON SITE?							
1. NO □ 2. Y	ES(specify	generator's fou	ır-digit SIC C odo):	:			
							
C. AREA OF SITE (in ecres)		D. ARE THE	RE BUILDINGS	N	THE SITE		
		1. NO	Z 2. YES	ope.	cify):		
		VI. CHAI	RACTERIZATIO	N	OF SITE ACTIVITY		
Indicate the major site activ	vity(ies)				rity by marking 'X' in the appro	pri	ate boxes.
A. TRANSPORTER	X.	B. \$1	ORER	×	C. TREATER	×	D. DISPÖSER
1.RAIL		PILE		T	1. FIL TRATION	Г	1. LANDFILL
2. SHIP		.SURFACE IM	POUNDMENT	†	2. INCINERATION	┪	2. LANDFARM
J. SARGE		. DRUMS		T	3. VOLUME REDUCTION	V	3. OPEN DUMP
4. TRUCK		TANK, ABOY	E SECUMO	╀╌	4.RECYCLING/RECOVERY	A	4. SURFACE IMPOUNDMENT
S. PIPELINE		. TANK, BELG	1.00	╆	S. CHEM./PHYS./TREATMENT		S. MIDNIGHT DUMPING
6. OTHER (specify):		OTHER (spec		┢	S. SIOLOGICAL TREATMENT		S. INCINERATION
	_ ⊢ '			┢	7. WASTE OIL REPROCESSING		7. UNDERGROUND INJECTION
			٠	⊢	A. SOLVENT RECOVERY		B. O THER(specify):
				┢	9. OTHER(epocity):	┰	
	- 1			┝		ł	
	1						
	-			1			
E. SUPPLEMENTAL REPORT	S: If the	ite fells within	say of the cales	rie:	s listed below, Supplemental Repor	18 1	must be completed. Indicate
which Supplemental Reports						'	
1. STOFAGE	2. INC	INERATION	3. LANDFIL	LL	4- SURFACE	S.	DEEP WELL
CHEM/BIO/		NDFARM	50 s. OPEN DI		9. TRANSPORTER		. RECYCLOR/RECLAIMER
- PHYS TREATMENT	<u></u>					, ,,	· neg i powie negenimen
A #1005 C		VII.	WASTE RELAT	ED	INFORMATION		
A. WASTE TYPE							
1. LIQUID	2. 50	LID	3. SLUGGE		4. GAS		
B. WASTE CHARACTERISTICS	3						
1. CORROSIVE	2. 161	HTABLE	3. RADIOA	CTI	VE 🔲 4. HIGHLY VOLATILE		
(V) S. TOXIC	☐ 6. RE	ACTIVE	7. INERT		B. FLAMMABLE		
•							
9. OTHER (opocity):							
C. WASTE CATEGORIES	iable? Soe	elly items such	to menifests. Im	vea	tories, etc. below.		
Ala		,			-		
100							
EPA Form T2070-3 (10-79)			PAGE	3 0)F 10	_	Continue On Revers

	int (specify unit of	meesu	r lo (m	veste !	y cate	gory	r; mark	'X' to	indic	: at	e which was	es are o	resent.	
. SLUDGE .	b. OIL			LVENT				EMICA			e. SOLIDS		f. 0T	HER
UNIT OF MEASURE	UNIT OF MEASURE		NIT OF	MEASI	JĀĒ		OUNT .	MEASU	A E	U	DSI - 60 Cubic	Hard	AMOUNT	EASUR
H PAINT,	X' OILY	· *	l., MAL	OGEN	ATED		(1) AC(05	·	A.	WDIC YE		X LABO	RATO MACE
(2) METALS SLUGGES	21 0 THER(0 POC	(ty):		·HAL	96HTD	•	(2) PIC	KLING JORS		X	(2) ASBESTO	•	(2) HOSP	TAL
(3) POTW			131076	ER(of	ecity)		(3) C A U	STICS			(3) MILLING/	MINE	(3) RADIO) A C T !
(4) ALUMINUM SLUDGE							(4) PES	TICIDE	\$		(4) FERROUS		(4) MUNIC	IPAL
(9) O THER (opecity):							(5) DYE	5/INK			ISI SMLTG. W		(5) OTHE	R(spe
-					•		(6) C Y A	NIDE		F	(6) OTHER(8)	pecify):		
							(71 PH€	NOLS						
							(8) HAL	OGEN:	s					
							(9) PC 8							
						Ц	(10) ME	TALS						
					<u>.</u>	H	111101	H € R(#)	ecity).					
D. LIST SUBSTANCES	OF GREATEST CON		HICH A	-	a-ferm		(place	in des	endin	01	der of hazard)			 _
1. SUBSTA	ANCE		nork 'X'			mark	(יאי	1 d.	4. C	AS	NUMBER	5. A	MOUNT	6. U
		LID	L10.			MED	. LOW							
Asbest	^ *	X			ner No.				187	8	6-24-8	25	1 -	140
11309011							1					¥		
· · · · · · · · · · · · · · · · · · ·													· · · ·	
		 					+	-						1
								1						
														-
							CRIPT							
FIELD EVALUATION hazard in the space p	TH HAZARDS	pl	N: Pla	i C^	.X' in	the C	er c	indica	-ge	N	. <u>T</u> +	, .	erent	
hazard in the space p A. Human HEAL? A. bc.	TH HAZARDS	pl	N: Pla	i C^	.X' in	the C	er c	indica	-ge	N	. <u>T</u> +	, .	erent	
hazard in the space p As bea	rovided.	pl	N: Pla	i C^	.X' in	the C	er c	indica	-ge	N	. <u>T</u> +	, .	erent	

1	Continued From Page 4	VIII. MAZARD DESCRIPTION (continued)	
•	B. NON-WORKER INJURY/EXPOSURE	THE TRACKS SENGIF I ION (CONTINUED)	
-	•.		•
	NA	~	·
	NIA		
		•	
.		<u></u>	
H	C. WORKER INJURY/EXPOSURE		
1		•	
ı	. N/W		
1			
1			
1		·	
١	·		•
1	•	•	
ł	O. CONTAMINATION OF WATER SUPPLY		
1			
1	. N/A		
\cdot	. P/R		
١			
ſ			
ł			
l			
١	E. CONTAMINATION OF FOOD CHAIN	, , , , , , , , , , , , , , , , , , ,	
	1		
1	· N/k		•
ł			
	·		
1	•		
1			
1			
ı	F. CONTAMINATION OF GROUND WATER		
ł	N/A		
Ĭ			
1			·
ŀ	G. CONTAMINATION OF SURFACE WATER	R	
ļ		-	
- [N/A		
1	•		
I			2
ı			0043
]			
Ł			
Ī	EPA Ferm T2070-3 (10-79)	PAGE S OF 10	Continue On Reverse

•	11 m = 1 2 m = 2 2 m = 2 3 m =	٠,
Continued From Front	AUT MATARA MENDETINA	· · · · · · · · · · · · · · · · · · ·
H. DAMAGE TO FLORA/FAUNA	VIII. HAZARD DESCRIPTION (continued)	
H. DAMAGE TO FLORA/FAUNA	©i Ami' • Sig	•
N/A	• • • •	
197		
		•
	Control of the Contro	
	. A 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997	
I. FISH KILL		
Ŋ/A	era line 1 de mario 1 de mario	
	er grande er	
J. CONTAMINATION OF AIR		
	5,0	
N/A		·
	•	
	<u>:</u>	
	este.	
·		
K. NOTICEABLE ODORS		
N/V	•	
,	The second secon	
		••
L. CONTAMINATION OF SOIL		
ines - the	asbestou is visible in	· · · · · · · · · · · · · · · · · · ·
5	CO 0131012 Ex	itte saat
:	·	
	•	
M. PROPERTY DAMAGE		
		ģ
NA		200
		. 0
		. 00 4
		•

ontinued From Page 6	- Control Cont			
	VIII. HAZARD DESCRIP	TION (continued)		
N. FIRE OR EXPLOSION	- 1 25 ·			
`\\\/A				
49/11				
	•			
0. SPILLS/LEAKING CONTAINERS/R	UNOFF/STANDING LIQUID			
		•	•	
	•			
n/ v				
		. :		
		<u>*</u>	•	
			•	
P. SEWER, STORM DRAIN PROBLEMS				
N/A				
,		•		
Q. EROSION PROBLEMS			 	
-	-21			
N/A	· ·			
	· · · · · · · · · · · · · · · · · · ·			
•	•			
	2 32 2 32 3 44			
R. INADEQUATE SECURITY				
			· · · · · · · · · · · · · · · · · · · 	
Just the st	to is early	accessibly	e from the	
Passau	⊅ ·	•		
, as acc	Rwer			
S. INCOMPATIBLE WASTES				
Te meamer Herr avairs				
41/2				
N/A	•			


Continued From I		. X. WATER AND HYDROL	GICAL DATA (c	ontinued)		
H. LIST ALL DRIN	KING WATER WEL	LS WITHIN A 1/4 MILE RADIUS OF	SITE			
1. #E LL	2. DEPTH (apocity unit)	(proximity le	LOCATION population/buildi	ndo)	NON-COM- MUNITY (merk 'X')	COMMUN ITY (mark 'X'
			=			
		<u>is</u>			_	
	<u> </u>	<u> </u>	•			
			·			
. RECEIVING WAT	ER .	L		·	L	<u>. </u>
1. NAME Bassair F	liver	2. SEWERS	Z 3. STREAMS			
. SPECIFY USE	ND CLASSIFICAT	ON OF RECEIVING WATERS	- ·			-
Driak	ing was	ter, Recreate	Sand			
		XI. SOIL AND VE	STATION DATA	<u> </u>		
OCATION OF SIT		B. KARST ZONE		IAR FLOOD PLAIN	O. WETLAND)
E. A REGULA	TED FLOODWAY	I F. CRITICAL HABITAT		ARGE ZONE OR SOLE SE	DURCE AQUIFER	
fark 'X' to indica	te the type(s) of	geological material observed			ent parts.	
A. CVERBUR	'x	B. BEDROCK (epocily balls)	×٠		(epocity below)	
1. SAND		Basalt				
2. CLAY						
3. GRAVEL		:* 				,
		XIII. SOIL PE	RMEABILITY	 · · · · · · · · · · · · · · · · · · ·		
A. UNKNOWN D. MODERATE RECHARGE ARI	[(10 to .1 cm/sec.	. LOW (.1 10 .001 cm/sec		C. HIGH (1000 to 1		•c.)
	₫.2. NO 3. C	OMMENTS:				
	_	OMMENTS:			- ai	4 4
NO ESTIMATES OF		recipy direction of score, e	endition of su	OPE. ETC.	recetation	<i>L</i> K
OTHER GEOLOG	, , ,	recipy direction of score, e est -to bank a	- 10077	MIC INVES		
PA Form T2070-3 (1 0-79)	PAGE	9 OF 10		Continue On	Reverse

L			XIV. PERMIT INF					
Ľ	ist all applicable permits h	eld by the site and	provide the related in	formation.			COMPLI	ANCE
	A. PERMIT TYPE	B. ISSUING	C. PERMIT	D. DATE	E. EXPIRATION DATE	F. IN COMPLIANCE (mark 'X')		
(.eRCRA, State, NPDES, etc.)	AGENCY	NUMBER	(mo.,dey,≜yr.)	(mo.,dey,&yr.)	YES	20	KNO
	NIA	•						}
-					 			
-			- 150 - 1 - 150 -					<u> </u>
		·						
			Fig.					
		·						1
-		YV PAST	REGULATORY OR E	NEODCEMENT AC	TIONS	i		——
-		7411791	ALGGERTONT ON E	TO OCCEMENT AC				
	_	Cypsum	Company	-, in a	greemen	t w	Uth	
	Notional National NJDEP, we Stabilize		Company over the	- , in a a asbestos	greemen dump	t wa	UTA	
			Company over the r bouk	asbestos	greemen dump	t wa	Uth	
			Company over the r book	asbestos	græmen dump	t wa	·	
			Company over the r bank	asbestos	greemen dump	t wa	cth.	
			Company over the ir bank	asbestes	greemeni dump	t wa	eth.	
			Company over the r bank	asbestos		t wa	eth.	
			Company over the ir bounk	asbestes		t wa	i th	
			Company over the ir bank	asbestos		t wa	· cth	
			Company over the r bank	asbestes		t wa	· cth	
			Company over the rounk	asbestes		t wa	i th	

EPA Form T2070-3 (10-79)


PAGE 10 OF 10







ERNARDS 155AIC



KEY MAP.

3B 002 0051

